


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-086	Smoke	9/11/2008	ADS/TM	S13CC1014MH	Dry	Yes	661.37



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-086	Smoke	9/11/2008	ADS/TM	S13CC1014MH	Dry	Yes	661.37

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13CC1026G1	S13CC1026MH	S13CC1004MH	57.91376	8
S13CC1004G1	S13CC1004MH	S13CC1014MH	281.5406	8
S13CC1022G1	S13CC1022MH	S13CC1026MH	149.3499	8
S11CC1019G1	S11CC1019MH	S13CC1022MH	172.5705	8

Observations & Photos

No smoke was observed during this test.

